


Silverado Module Programming Availability Matrix (SPS/TLC)

This bulletin is to advise of the availability of the Australian calibrations for the RHD converted Silverado 1500 and 2500.

Before any programming on a GMSV Silverado, Technician's must check the below matrix for the availability of the calibration status, and whether to proceed with programming from TLC. If you have any issues, please email us at <u>gmserviceinfoau@gm.com</u>



GMSV has created this matrix and will continue to update this matrix as calibrations become available for each Model Year and as new models are introduced. This will be a live document and we advise you not to print out this matrix, as it will change over time!

If it is Green/Ok on the above matrix, you can proceed with programming from TLC. If it is Red - NOT OK, please contact <u>gmserviceinfoau@gm.com</u> for direction.